

Michael O. Leavitt Governor Kathleen Clarke

Executive Director

Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)



INSPECTION REPORT

Partial X	XX Complete _	Exploration
Inspection Date:	02/05/2002 / T	Time: 9:30 – 11:30
D	ate of Last Inspe	ection: 01/02/2002

Mine Name: Hiawatha Complex	County: Carbon	Permit Number: <u>C/007/011</u>					
Permittee and/or Operator's Name: Hiawatha Coal Company							
Business Address: P.O. Box 1202, Huntington, Utah 84528							
Company Official(s): Nate Finley							
State Official(s): Karl R. Houskeeper	Fed	eral Official(s): None					
Weather Conditions: Clear, Temp 30 – 35°	F						
Type of Mining Activity: Underground XX	X Surface Prep	PlantOther					
Existing Acreage: Permitted 12,177 Disturbed 290 Regraded Seeded							
Status: Active Reclamation							

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE				
2.	SIGNS AND MARKERS	[XX]	\Box	[XX]	
3.	TOPSOIL	· [_]	\Box		
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]		[XX]	
b.	SEDIMENT PONDS AND IMPOUNDMENTS	· [_]			
c.	OTHER SEDIMENT CONTROL MEASURES				
d.	WATER MONITORING	[XX]		[XX]	
e.	EFFLUENT LIMITATIONS	- [_]			
5.	EXPLOSIVES				
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES				
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]		[XX]	
8.	NONCOAL WASTE	[XX]		[XX]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE				
11.	CONTEMPORANEOUS RECLAMATION				
12.	BACKFILLING AND GRADING	\Box			
13.	REVEGETATION	\Box			\Box
14.	SUBSIDENCE CONTROL	<u> []</u>	\Box		
15.	CESSATION OF OPERATIONS				
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING				
b.	DRAINAGE CONTROLS			\Box	\Box
17.	OTHER TRANSPORTATION FACILITIES				
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	\Box			
19.	AVS CHECK (4th Quarter- April, May, June)			\Box	· [_]
20.	AIR QUALITY PERMIT				\Box
21.	BONDING & INSURANCE				

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: C/007/011

DATE OF INSPECTION: 02/05/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

2. SIGNS AND MARKERS

Checked the mine ID signs at all public entrances. The signs contained the appropriate information. All other required signs that were observed were in accordance with the coal rules.

4A. HYDROLOGIC BALANCE: DIVERSIONS

While inspecting Refuse Pile No. 1 a partial obstruction of a 24" culvert was noted. The 24" culvert is located on the northeast side of Refuse Pile No. 1. This structure is identified on Exhibit V-9 of Chapter V of the approved MRP. The obstruction did not constitute a violation and the operator indicated that it would be removed. The operator was also advised to monitor the ditch leading to this culvert. Presently, the ditch has frozen runoff in it and it was not possible to determine if it meets the design within the approved MRP.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Third quarter 2001 water quality information has been submitted to the EDI system. This information was viewed prior to the inspection. Fourth quarter water monitoring has been done and is in the process of being submitted to the Division.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

Inspected Refuse Pile No. 1. No visible hazards or smokers were noted. Concerns regarding some of the diversions are noted above. Inspected Slurry Pond No. 1. No visible hazards or smokers were noted.

8. NONCOAL WASTE

Instructed the operator to gather and contain several empty 55 gallon drums that were dispersed around the perimeter of Refuse Pile No. 1 and Slurry Pond No. 1. Recent heavy winds moved the drums away from the Heavy Equipment Shop where they were originally located.

Inspector's Signature:

Karl R. Houskeeper

#40

Date: February 6, 2002

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

ce: James Fulton, OSM

Elliot Finley, Hiawatha

Price Field office

O:\007011.HIA\Compliance\2002\p 0205.doc